

**Precautionary Drinking Water Advisories (PDWA) and Emergency Boil Water Orders (EBWO)  
Currently in Effect for Waterworks that are Regulated by the Saskatchewan Ministry of Environment**

**December 29, 2011 - 5:00 P.M.**

**NOTICE:** While Saskatchewan Ministry of Environment (Environment) makes every effort to post and remove listings of Precautionary Drinking Water Advisories (PDWA) and Emergency Boil Water Orders (EBWO) in a timely manner, from time to time circumstances may arise that prevent timely revisions to this website. In the event consumers require additional information regarding application of a PDWA or EBWO, they are advised to contact their water supplier or Environment as outlined on the site-specific PDWA or EBWO (see: [http://www.saskh2o.ca/pdwa\\_ebwo.asp](http://www.saskh2o.ca/pdwa_ebwo.asp)). If questions arise after hours regarding a PDWA or EBWO, an Environment Environmental Project Officer may be reached by calling 1-800-667-7525.

<b>Community</b>	<b>Date Issued</b>	<b>PDWA</b>	<b>EBWO</b>	<b>PDWA Issued due to planned system startup OR maintenance</b>	<b>Comments</b>
9th Avenue Viaduct Water Co-operative (Moose Jaw)	12-Dec-05	1			PDWA issued <b>December 12, 2005</b> due to low chlorine levels.
Alida, Village of	25-Nov-11	1			PDWA issued <b>November 25, 2011</b> due to the seven (7) service connections not receiving continuously disinfected/treated potable water.
Antler, Village of	17-Nov-11	1			PDWA issued on <b>November 17, 2011</b> due to the community no longer having a certified operator in charge of the waterworks facility, and also, recent analysis of the water indicates an exceedance of "Trihalomethanes".
Battlefords Provincial Park (seasonal shutdown)	5-Oct-11	1			PDWA issued <b>October 5, 2011</b> due to intermittent insufficient disinfection levels in the distribution system.
Buffalo Pound Provincial Park	26-Sep-2011	1			PDWA issued on <b>September 26, 2011</b> due to low chlorine residual in the water.
Caribou South Water Users Co-operative (Moose Jaw)	30-Nov-2005	1			PDWA issued <b>November 30, 2005</b> due to low chlorine residuals.
Caribou West Pipeline Co-operative (Moose Jaw)	23-Nov-2005	1			PDWA issued <b>November 23, 2005</b> due to low chlorine residuals.
Coderre, Village of	1-Dec-2010	1			PDWA issued on <b>December 1, 2010</b> due to risks associated with the Village well being potentially under the direct influence of surface water combined with the lack of treatment at the water treatment plant.
Cole Bay, Northern Village of	28-Dec-2011			1	PDWA issued effective <b>December 29, 2011</b> due to the planned shutdown of the water treatment plant as part of the ongoing construction process.
Craik, Town of	17-Aug-2010	1			PDWA issued on <b>August 17, 2010</b> due to a system upset and updated on <b>Sept 9, 2010</b> for failing to meet Minimum Disinfection Levels (Ozone).
Creelman	11-Sep-2010	1			PDWA issued due to high turbidity.
Darling's Beach, Hamlet of - <b>DO NOT DRINK THE WATER</b>	17-Jun-2008	1			PDWA ( <b>DO NOT DRINK THE WATER</b> ) issued on <b>June 17, 2008</b> due to elevated levels of uranium in the well water.
Dodd's Subdivision (607205 Sask. Ltd.) RM of Lumsden	25-May-2010	1			PDWA issued on <b>May 25, 2010</b> due to possible infiltration of runoff water in the waterworks system causing high turbidity.
Duff, Village of	22-Jul-2009	1			PDWA issued <b>July 22, 2009</b> due to high turbidity.
Dufferin Water Association water pipeline	30-Nov-2011	1			PDWA issued <b>November 30, 2011</b> due to seasonal low disinfection levels.
Dundurn Rural Water Utility Pipeline System, Phase 3 extension only.	4-Oct-2011	1			PDWA issued <b>October 4, 2011</b> due to the startup of a new pipeline system. <b>UPDATED December 8, 2011</b> now includes DRWU Pipeline system, Phase 3 Extension, Blackstrap Prov Park ext line & system within RM of Rosedale (except main line to the Town of Hanley)
East Barrier Water Co-op <b>DO NOT DRINK THE WATER</b>	5/6/2008 (PDWA) 22-Sept-2008 (DN Drink Order)	1			PDWA issued due to seasonal start-up. Upgraded to <b>DO NOT DRINK THE WATER</b> on <b>September 22, 2008</b> due to numerous positives.
Eight Mile Pipeline Association Inc.	20-Dec-2011	1			PDWA issued <b>December 20, 2011</b> due to seasonal low chlorine residuals in the distributed water.
Elstow North Rural Water Utility	16-Nov-2011	1			PDWA issued on <b>November 16, 2011</b> due to inadequate chlorine levels in the distribution system.
Fenwood, Village of	29-Sep-2011	1			PDWA issued on <b>September 29, 2011</b> due to turbidity at the water treatment plant and chlorine levels not meeting the regulatory standards throughout the distribution system.
Francis, Town of	27-Nov-2011	1			PDWA issued <b>November 27, 2011</b> due to an increase in turbidity and lack of certified operator required and therefore the safety of the drinking water supply cannot be ensured at all times.
Goodeve, Village of	28-Dec-2011	1			PDWA issued <b>December 28, 2011</b> due to a complete distribution depressurization.
Greenstreet, Hamlet of	18-Apr-2007	1			Reason for PDWA changed to: new source water and treatment plant upgrades.
Hazlet, Village of	7-Dec-2010	1			PDWA issued on <b>December 7, 2010</b> due to elevated turbidity.
Hepburn, Village of	5-Dec-2011	1			PDWA issued effective <b>December 7, 2011</b> due to unknown water quality from start-up of the new waterworks distribution system and system connections.
High Country Estates distribution system	20-Jul-2011	1			PDWA issued <b>July 20, 2011</b> due to frequent turbidity analysis results above regulated turbidity values.
Highway #1 West Water Co-operative <b>NW of Moose Jaw</b>	30-Nov-2005	1			PDWA issued <b>November 30, 2005</b> due to low chlorine residuals.
Highway 41 Water Utility Pipeline System	11-Mar-2010	1			PDWA issued on <b>March 11, 2010</b> due to the startup of a new pipeline system.
Hillsvale Colony distribution system	29-Apr-2011	1			PDWA issued <b>April 29, 2011</b> due to system start up and inability to meet disinfection requirements.

Huron Colony	5-Feb-2007	1			PDWA issued due to lack of continuous chlorination of the drinking water.
Khedive, Hamlet of	8-Jan-2010	1			PDWA issued <b>January 11, 2010</b> due to turbidity levels exceeding the provincial water quality standard going into the waterworks system.
Kuroki, Hamlet of (RM of Sasman #336)	11-May-2011	1			PDWA issued <b>May 11, 2011</b> despite the good efforts of the operator to main safe drinking water, there has been a deviation from normal operation resulting in higher than normal turbidity levels.
Lac Pelletier Regional Park - Ona's and Darling's Beach <b>DO NOT DRINK WATER</b>	2-Apr-2009	1			<b>"DO NOT DRINK THE WATER"</b> PDWA issued on <b>April 2, 2009</b> due to elevated levels of uranium in the well water.
Lakeside RV Trailer Park - Elbow	14-Dec-2011	1			PDWA issued <b>December 14, 2011</b> due to low seasonal disinfection levels.
Mainprize Regional Park	10-Aug-2010	1			PDWA issued on <b>August 10, 2010</b> due to an upset condition at the park's Water Treatment plant.
McCord, Hamlet of	3-Sep-2009	1			PDWA issued on <b>September 3, 2009</b> due to high turbidity levels in the waterworks system.
Medstead, Village of	29-Dec-2011	1			PDWA issued <b>December 29, 2011</b> due to a complete system depressurization.
Melfort (applicable to residents south of Melfort on the Agriculture Canada extension)	17-Dec-2004	1			PDWA issued due to low chlorine residuals being experienced following a water main repair of the distribution system.
Michel Village, Northern Hamlet of	1-Sep-2011			1	PDWA issued <b>September 1, 2011</b> due to improvements and cleaning activities in the treated water reservoir at the water treatment plant.
Minton, Village of	23-Sep-2010	1			PDWA issued on <b>September 23, 2010</b> due to turbidity levels exceeding the provincial water quality standard.
Moose Jaw (affects customers west of 24th Avenue West).	7-Oct-2008	1			PDWA issued due to low chlorine levels.
North Valley Waterline Co-operative System	13-Oct-2009	1			PDWA issued due to low chlorine residuals in the distribution system.
Ormiston, Hamlet of (RM of Excel # 71)	1-Dec-2010	1			PDWA issued on <b>December 1, 2010</b> due to risks associated with the Hamlet well being potentially under the direct influence of surface water combined with the lack of treatment at the water treatment plant.
Pasqua Water Users Co-operative	8-Oct-2009	1			PDWA issued on <b>October 8, 2009</b> due to low chlorine residuals in parts of the distribution system.
Patuanak, Northern Hamlet of	24-Aug-2010			1	PDWA issued on <b>August 24, 2010</b> due to planned system maintenance of the waterworks, and includes cleaning the treated water reservoir and distribution system swabbing.
Pleasantdale, Village of	2-Jul-2010	1			PDWA issued on <b>July 2, 2010</b> due to flooding of the well pit. UPDATED <b>March 29, 2011</b> due to the Village unable to control turbidity.
Radville, Town of	28-Jan-2010			1	PDWA issued on <b>January 28, 2010</b> due to the incorporation and start up of the new water treatment process. <b>UPGRADED</b> to EBWO on <b>April 13, 2011</b> due to high turbidity from the current flood.
Redthorpe Utility Board Water Pipeline	8-Feb-2010	1			PDWA issued <b>February 8, 2010</b> due to low disinfectant levels in the waterworks distribution system.
Redvers ( <b>Only affects the following users supplied by Redvers:</b> Couture Motors, Real Wolensky, Prosper Tractor Ltd., Redvers Co-op Associated Ltd. - Bulk Fuel)	21-Feb-2006	1			Town has advised it is unable to maintain chlorine levels at regulatory requirements.
Regina South Public Utility Board - <b>REVISED</b>	6-Nov-2006	1			PDWA issued due to low chlorine residuals on the pipeline.
Riverside Estates	15-May-2003	1			PDWA issued due to insufficient treatment.
Roche Percee, Village of	11-May-2011	1			PDWA issued <b>May 11, 2011</b> due to the Village's well being at risk of surface water infiltration due to flooding. UPDATED
Rowan's Ravine Provincial Park	Reissued 10-Aug-2011 28-June-2010 reissued 17-June-2011	1			PDWA issued on <b>June 28, 2010</b> due to risk of contamination due to high water levels around the well housing. <b>Re-Issued</b> PDWA on <b>June 17, 2011</b> due to the threat of contamination due to flooding of Last Mountain Lake. <b>Re-Issued PDWA on August 10, 2011</b> due to threat of contamination due to flooding of Last Mountain Lake.
SaskWater Saskatoon East and West Raw Water Lines. <b>The West Raw Water Line will exclude the following: Cedar Villa Estates, Village of Vanscoy and the PSC Cory and Agrium Vanscoy Potash Mines as these sites have their own approves waterworks.</b>	15-May-2008	1			PDWA issued on <b>May 15, 2008</b> . The Ministry of Environment has reviewed information regarding the SaskWater Saskatoon East and West Raw Water Supply lines. The water treatment process is inadequate to ensure hygienic or potable water use.
SHL Rural Pipeline Association - Muenster Line	11-Feb-2004			1	PDWA issued due to the pressurization of the drinking water distribution system along the Muenster line.
Storthoaks, Village of	13-Oct-2009	1			PDWA issued <b>October 13, 2009</b> due to the presence of unacceptable coliform bacteria in repeat water samples taken from the water treatment plant.
Stoughton	20-Aug-2009	1			PDWA issued due to the inability to maintain the turbidity under 1.00 NTU.
Sunset View Beach, Resort Village of - Public Utility Board	19-Dec-2011	1			PDWA issued <b>December 19, 2011</b> due to elevated turbidity levels in the distribution system which may impact the effectiveness of the chlorine disinfection process.
Tobin Lake <b>DO NOT DRINK THE WATER</b>	8-Mar-2006	1			PDWA issued <b>March 8, 2006</b> due to high fluoride levels.
Uranium City	30-May-2001	1			Lacks minimum water treatment processes.
Valley Ridge Community Co-operative	13-Jan-2009	1			PDWA issued due to low chlorine residuals in their water distribution system.

Welwyn, Village of	27-Jan-2010	1			PDWA issued on <b>January 27, 2010</b> due to a number of equipment failures and issues causing high turbidity combined with substandard water quality to enter the distribution system.
Willow Park Colony, Hutterian Brethren Church of	15-Jan-2010	1			PDWA issued on <b>January 15, 2010</b> due to unknown bacteriological water quality and no disinfection with maintained chlorine residuals.
Yarbo	9-May-2008	1			PDWA issued due to higher than normal turbidity levels.
Yellow Grass, Town of	11-Aug-2011	1			PDWA issued on <b>August 11, 2011</b> due to maintenance and upgrading of the water system.
<b>Advisories/Orders Currently in Effect:</b>		<b>60</b>	<b>1</b>	<b>4</b>	

**Precautionary Drinking Water Advisories and Emergency Boil Water Orders currently in Effect for Public Water Supplies that are Regulated by the Regional Health Authorities in Saskatchewan**

**December 29, 2011 - 5:00 P.M.**

<b>Public Water Supply</b>	<b>Date Issues/Issued By</b>	<b>PDWA</b>	<b>EBWO</b>	<b>Comments</b>	<b>Comments</b>
All Season Service, Candle Lake SK	17-Feb-2011 Prince Albert Parkland HR		1		EBWO issued on <b>February 17, 2011</b> due to the presence of contaminants.
All Seasons Resort - Turtle Lake	14-July -11 Prince Albert Parkland Health		1		EBWO issued <b>July 14, 2011</b> as the seasonal campground system does not meet minimum treatment/design requirements.
Angler Trail Resort (Darsana) - Premise #22007	11-June-2009 Athabasca/Keewatin/Mamawetan	1			PDWA issued on <b>June 11, 2009</b> due to the presence of coliforms.
Arctic Lodges Ltd. - (GPS 56.9933/102.337)	4-Sept-10 Athabasca/Keewatin/Mamawetan	1			PDWA issued due to the presence of total coliform.
Athabasca Camps Inc. - Engler Lake - Public Water Supply - #15232	1-July-07 Athabasca/Keewatin/Mamawetan		1		EBWO issued due to the presence of total coliform and E.Coli.
Balgonie Shell Well	11-May-11 Regina Qu'Appelle HR	1			PDWA issued <b>May 11, 2011</b> remains in effect until safe water is evidenced as it does not meet monitoring requirements.
Baptiste Lake Lodge Ltd. (Premise #22000)	5-June-2009 Athabasca/Keewatin/Mamawetan	1			PDWA issued due to overgrowth of total coliform.
Bayside Bed and Breakfast - Premise 15494; Latitude/Longitude 54.4509/105.982	16-June-2008 Athabasca/Keewatin/Mamawetan	1			PDWA issued due to the presence of total coliform.
Besnard Lake - Campground; Premise 15994; Latitude/Longitude: 55.4087/106.066	2-Sept-2011 Mamawetan Churchill River		1		EBWO issued <b>August 29, 2011</b> due to total coliform and E coli.
Big Sandy Outdoor Adventures (Public Water Supply #15820)	26-June-2006 Mamawetan Churchill River HR		1		EBWO issued on <b>June 26, 2006</b> due to the presence of E.Coli.
Bigstone Outfitters	17-June-2011 Mamawetan Churchill River HR	1			PDWA issued effective <b>June 17, 2011</b> .
Black Bear Island Lodge - Public Water Supply #14691	8-June-2007 Athabasca/Keewatin/Mamawetan	1			PDWA issued due to poor bacteriological results.
Boggy Creek Wellfield - two specific rural customers outside Regina	7/24/2006 Regina Qu'Appelle HR	1			PDWA issued due to well operation.
Brunansky's Foster Lake Lodge - Public Water Supply #17234	21-June-07 Athabasca/Keewatin/Mamawetan	1			PDWA issued due to the presence of coliform bacteria.
Buchanan, RM of #304 Well at NE 33-33-05 W2	16-June-2010 Sunrise HR		1		PDWA lifted on <b>June 16, 2010</b> and an EBWO issued on <b>June 16, 2010</b> due to the presence of contaminants namely, total coliform and E.Coli bacteria.
Buchanan, RM of #304 Well at SE 22-30-06 W2 (Premise 13623)	25-March-2011 Sunrise HR	1			PDWA issued <b>March 25, 2011</b> due to the presence of coliform bacteria.
Buchanan, RM of #304 Well at SE 23-32-4 W2nd (Premise 13621)	25-March-2011 Sunrise HR	1			EBWO issued on <b>May 13, 2010</b> due to the presence of E. coli has been rescinded and replaced with a PDWA on <b>March 25, 2011</b> .
Buffalo Hump Community Well, RM of Livingston #331 (NW 1/4 7-34-32-W2M)	18-March-2009 Sunrise HR	1			PDWA issued on <b>March 18, 2009</b> due to the presence of coliform bacteria as well as nitrate concentration.
Burbidge Lake Lodge Ltd.	25-June-2007 Athabasca/Keewatin/Mamawetan		1		EBWO issued due to positive E.Coli. result.
Burym Community Well #13739; SW 26-36-3-W2, RM of Clayton #333	8-Aug-2008 Sunrise HR	1			PDWA issued due to the presence of coliform.
Camp Grizzly (Premise #12291 Latitude/Longitude 54.5633/103.52)	9-June-2009 Athabasca/Keewatin/Mamawetan	1			PDWA issued due to overgrowth of total coliform.
Canadian Wilderness Sports Camp; Long/Lat: 55°11'23"/105°40'05"	20-June-2008 Athabasca/Keewatin/Mamawetan	1			PDWA issued due to the presence of total coliform.
Cando Community School & Cando Childcare Centre	16-Sept-2010 Heartland HR	1			PDWA issued on <b>September 16, 2010</b> due to unsatisfactory bacteriological results indicating coliform organisms.
Canora Beach Resort - Public Water Supply - SE 17-30-5-W2nd	4-Sept-2009 Sunrise HR	1			PDWA issued on <b>September 4, 2009</b> due to the presence of coliform bacteria.

Carson's South Camp - Public Water Supply #15203	2-Feb-2010 Mamawetan Churchill River HR		1		EBWO issued <b>June 7, 2007</b> due to the presence of total coliform and E.Coli.
Cedar Lodge - PW SW 5-33-3 W3rd Facility #24644 RM of Dundurn #314	10-May-11 Saskatoon HR	1			PDWA issued <b>May 10, 2011</b> due to the lack of minimum treatment.
Centre Communautaire - Cistern	22-Sept-11 Saskatoon HR	1			PDWA issued <b>September 22, 2011</b> due to the presence of contaminants, namely E coli and total Coliform in the public
Cherrydale Golf and Campground	15-June-07 Sunrise HR	1			PDWA issued due to poor bacteriological results.
Chilly's Pub and Grill (RM No. 183)	25-Jun-09 Sunrise HR	1			PDWA issued on <b>June 25, 2009</b> due to the presence of coliform bacteria.
Christopher Lake Manor	1-June-10 Prince Albert Parkland		1		EBWO issued on <b>June 1, 2010</b> due to E. coli detected in drinking water system.
Churchill River Voyager Lodge - Public Water Supply 15570	1-June-2007 Mamawetan Churchill River HR	1			EBWO issued <b>June 24, 2011</b> .
Churchill River Wilderness Camp - Public Water Supply 14673; Lat/Long: 55.7028/106.739	18-June-2008 Athabasca/Keewatin/Mamawetan		1		PDWA issued <b>June 18, 2008</b> due to the presence of total coliform.
Clark Lake Lodge - Public Water Supply #12634	17-Jul-09 Athabasca/Keewatin/Mamawetan	1			PDWA issued due to the presence of coliform bacteria.
Clayton, RM of #333, Danbury Community Well, Facility #13741	22-June-07 Sunrise HR	1			PDWA issued due to poor bacteriological results.
Clearwater Lake Hotel - Clearwater Lake Regional Park	18-May-2011 Heartland HR	1			PDWA issued <b>May 18, 2011</b> due to the absence of water sample submissions and an absence of information regarding the water source.
Collins Camp and Outfitters Inc.; Premise 14516; Besnard Lake	16-June-2008 Athabasca/Keewatin/Mamawetan	1			PDWA issued due to the presence of total coliform.
Collins Camps & Outfittings Inc. (Premise #21959)	13-June-2009 Athabasca/Keewatin/Mamawetan	1			PWDA issued due to the presence of coliform bacteria.
Cowan Dam Campground - Public Water Supply - #17238	30-May-08 Athabasca/Keewatin/Mamawetan		1		EBWO issued <b>May 30, 2008</b> due to the presence of coliform.
Craven Country Jamboree - new Campsite location RM of Lumsden #189 NE 31-19-21 W2nd	12-July-11 Regina Qu'Appelle HR	1			PDWA issued <b>July 11, 2011</b> due to season start-up.
Craven Country Jamboree Well Water Supply services and buildings on Main Street	12-July-11 Regina Qu'Appelle HR		1		EBWO issued <b>July 12, 2011</b> due to start-up of water system delayed as a result of flood waters.
Cree Lake Lodge 2009 Ltd. PW#15708	25-June-2010 MCCRHA	1			PDWA issued on <b>June 25, 2010</b> .
Cree River Lodge Inc. - Public Water # 15027	17-Jul-09 Athabasca/Keewatin/Mamawetan		1		EBWO issued due to the presence of coliform bacteria and e.coli.
Crystal Lake Golf & Country Club Well (RM of Keys No. #303)	17-Jun-09 Sunrise HR	1			PDWA issued due to high nitrate count.
Crystal Lodge Ltd. Ispatamow Island - Cree Lake	28-June-10 Athabasca/Keewatin/Mamawetan		1		PDWA issued due to poor bacteriological results. Amended to an EBWO on <b>June 28, 2010</b> due to the presence of contaminants in a water sample, namely coliform in the public water supply.
D & D Camps - Duplex Cabin KS - Longitude/Longitude 57.743/103.954	14-June-08 Athabasca/Keewatin/Mamawetan		1		EBWO issued on <b>June 30, 2008</b> due to the presence of total coliforms and E.Coli.
Daly Lake Outpost Camp	25-June-07 Athabasca/Keewatin/Mamawetan	1			issued due to poor bacteriological results.
Davin Lake Lodge (Premise # 16058 - Latitude/Longitude: 56.9169/103.917)	13-June-09 Athabasca/Keewatin/Mamawetan	1			PDWA issued due to the presence of coliform bacteria.
Deception Lake Lodge - Public Water Supply #15772	4-June-2007 Mamawetan HR	1			PDWA issued on <b>June 5, 2007</b> due to poor bacteriological results.
Deschambault Lake Resort PW #: 12334	8-July-11 MCCRHA		1		EBWO issued <b>July 8, 2011</b> .
Domremy Beach Resort Well	11-April-2011 Saskatoon HR	1			PDWA issued on <b>April 11, 2011</b> due to a lack of compliance in regards to water sampling.
Drinking Falls Lodge Premise #14696	24-June-2010 Mamawetan Churchill River HR		1		EBWO issued <b>June 24, 2010</b> .
Ebon Stables Concession - Cistern RM of Corman Park #344 SE 10-36-4 W3rd	16-April-2010 Saskatoon HR	1			PDWA issued effective <b>April 16, 2010</b> due to a lack of compliance in regards to water sampling.
Ena Lake Lodge - Public Water Supply #15024	4-July-07 Athabasca/Keewatin/Mamawetan	1			PDWA issued due to the presence of total coliform.
Eston Regional Park	21-May-10 Heartland HR	1			PDWA issued <b>May 21, 2010</b> due to untreated surface water.
Falkowski, June Approved Home of Well located - SW 14-28-05 W2	19-Mar-08 Sunrise HR	1			PDWA issued due to lack of water sampling and a history of unacceptable test results indicating the presence of E.coli and Coliform bacteria.

Fleming Tourist Reception Centre Well NE 26-12-30 W2nd Premises #9879	14-July-2010 Regina Qu'Appelle HR	1			PDWA issued on <b>July 14, 2010</b> due to the potential presence of coliform bacteria in the public water supply due to flooding of the well from very high ground water.
Foster River Camps - Public Water Supply 15159	8-June-2007 Athabasca/Keewatin/Mamawetan		1		PDWA lifted on <b>June 23, 2009</b> and an EBWO issued on <b>June 23, 2009</b> due to the presence of E.Coli.
George Lake Camp Outfitting (Public Water Supply #15654)	10-June-2006 Athabasca/Keewatin/Mamawetan		1		EBWO issued on <b>June 12, 2006</b> due to the presence of E.Coli.
Glen Harbour Kids Camp Well Parcel A, Plan DL 5102	26-May-2010 Regina Qu'Appelle HR	1			PDWA issued on <b>May 26, 2010</b> due to the presence of contaminants, namely coliform bacteria in the public water supply.
Good Spirit Bible Camp NE 08-29-05 W2	15-July-08 Sunrise HR	1			PDWA issued on <b>July 15, 2008</b> due to lack of water sampling.
Good Spirit Lake Provincial Park Recreation Hall and Administrative Offices	20-Mar-08 Sunrise HR	1			PDWA issued on <b>March 20, 2008</b> due to a lack of sampling.
Grand Slam Lodge - Public Water Supply #15016 (GPS 57.0758/102.028)	16-July-2007 Athabasca/Keewatin/Mamawetan		1		EBWO issued due to the present of total coliform and E.Coli.
Green Acres Golf and Country Club Well	27-Aug-2010 Regina Qu'Appelle HR	1			PDWA issued August 27, 2010 due to the presence of coliform bacteria in the public water supply. <b>UPDATED September 16, 2011</b> , despite the good efforts of the operator to maintain safe drinking water, there has been a deviation from normal operation, presence of contaminants, namely coliform bacteria in the public water supply.
Green Lake Lodge	02-July-2009 Athabasca/Keewatin/Mamawetan	1			issued due to poor bacteriological results.
Haskins Bay Fly-in	17-June-2011 Mamawetan Churchill River HR	1			PDWA issued effective <b>June 17, 2011</b> .
Hawkrock Wilderness Adventure Ltd. - Public Water Supply #15003	4-July-07 Athabasca/Keewatin/Mamawetan	1			PDWA issued <b>July 4, 2007</b> due to the presence of total coliform.
Hepburn Arena Well Premise #6661 RM of Hepburn #404	2-Nov-2009 Saskatoon HR	1			PDWA issued <b>November 2, 2009</b> due to the presence of total coliforms.
Hepburn Lake Lodge - Public Water Supply #15597 (GPS: N55.88119-W105.00213)	6-June-2006 Athabasca/Keewatin/Mamawetan		1		EBWQ issued due to the presence of E.coli.
Hepburn School Well	2-Nov-09 Saskatoon HR	1			PDWA issued <b>November 2, 2009</b> due to the presence of total coliform.
Hepburn, Village of	2-Nov-09 Saskatoon HR	1			PDWA issued <b>November 9, 2009</b> due to the presence of total coliform.
Hillcrest Hutterite Colony-Hygienic Portion	6-June-05 Saskatoon HR	1			PDWA issued for the hygienic portion of the Hillcrest Hutterite Colony waterworks.
Hinchliffe Well, RM of Preeceville - Facility #13800, NE 33-35-5- W2M	30-Jul-2009 Sunrise HR	1			PDWA issued due to the presence of bacteria.
Indian Head Camp Adventures Premise PW: 15245	30-Jul-2010 Athabasca/Keewatin/Mamawetan		1		EBWO issued <b>July 30, 2010</b> due to the presence of contaminants in the water.
Jan Lake Convenience Store PW #15974	2-Sept-2011 Mamawetan Churchill River		1		EBWO issued <b>September 2, 2011</b> due to total coliform and E coli.
J.D.'s Tower Lodge (Meadow Lake)	8/6/2003 Athabasca/Keewatin/Mamawetan		1		EBWO issued as system is not in compliance with <i>The Public Health Act</i>
Johnson River Camp	7-June-2010 Athabasca/Keewatin/Mamawetan		1		EBWO issued due to the presence of contaminants
Jim's Camp - Public Water Supply #15228 (GPS: N55.40008-W104.36738)	29-May-2006 Athabasca/Keewatin/Mamawetan		1		EBWO issued due to the presence of E.Coli.
Jug Bay Sport Fishing Premise# 21119	30-Jul-2010 Mamawetan Churchill River		1		EBWO issued on <b>July 30, 2010</b> due to be presence of contaminants in the water.
Kandahar Waterworks Well	Saskatoon HR 29-April-2010	1			PDWA issued on <b>April 29, 2010</b> due to water contamination.
Kamkota Lodge - Public Water Supply #12726	31-May-08 Athabasca/Keewatin/Mamawetan		1		EBWO issued <b>May 31, 2008</b> due to the presence of total coliform and E.Coli.
Keefe Lake Camp PW#15208	14-Jul-2011 Mamawetan Churchill River	1			PDWA issued <b>July 14, 2011</b>
Kennedy Well SW 28-12-13 W2nd RM of Wawken #93	24-June-2010 Sun Country HR		1		EBWO issued on <b>June 24, 2010</b> .
King George #256, RM of SW 27-25-10 W3rd Premise #22952	25-Jun-2010 Heartland HR	1			PDWA issued on <b>June 25, 2010</b> due to a positive water sample of greater than 100 coliforms.
Kingfisher Lodge - Public Water Supply #15598 (GPS: N55.42200-W102.10200)	11-June-11 Mamawetan Churchill River	1			PDWA issued June 11, <b>2011</b> .
Lady Lake Hamlet Well, RM of Preeceville #334 - Facility #13799, SE 27-35-5-W2nd	30-Jul-2009 Sunrise HR	1			PDWA issued due to high nitrate count.

Lady Lake Regional Park Well, RM of Preeceville #334, Facility #13511	15-June-2009 Sunrise HR	1			PDWA issued on <b>June 15, 2009</b> due to the presence of bacteria.
La Fleur Outdoor Adventures	14-July-09 Athabasca/Keewatin/Mamawetan		1		PDWA issued due to the presence of total coliform. PDWA lifted on <b>July 16, 2009</b> and upgraded to EBWO due to the presence of e.coli.
Lake Athabasca Lodge (Public Water Supply #15383)	21-June-06 Athabasca/Keewatin/Mamawetan		1		EBWO issued <b>June 21, 2006</b> due to the presence of E.Coli.
Langenburg, RM of #181	11-June-09 Sunrise HR	1			PDWA issued due to the presence of coliform bacteria.
Lindbergh's Reindeer Lake Lodge PW 15132 Latitude/Longitude: 57.2847/102.533	10-June-08 Mamawetan Churchill River HR	1			PDWA issued <b>June 10, 2008</b>
Lindbergh's Reindeer Lake Lodge - Reilly Lake Outpost Premise #23464	16-July-07 Mamawetan Churchill River HR	1			PDWA issued <b>June 24, 2010</b> .
Lipton, RM of #217 Public Well located at NE 4-22-15 W2nd	30-Sept-2010 Regina Qu'Appelle HR		1		EBWO issued on <b>September 30, 2010</b> due to the presence of E. coli bacteria in the public water supply.
Lloyd Lake Lodge (GPS: N57.33715 W109.01407)	12-June-2006 Mamawetan Churchill River HR		1		EBWO issued <b>June 12, 2006</b> due to the presence of E.Coli.
Lone Wolf Camps	25-June-07 Athabasca/Keewatin/Mamawetan		1		EBWO issued <b>June 25, 2007</b> due to positive E.Coli. result.
Luseland Campground (Town of Luseland & RM of Progress #351 NW 8-36-24 W3rd)	2-July-10 Heartland HR	1			PDWA issued on <b>July 2, 2010</b> due to a positive water sample of greater than 100 coliforms.
MacPherson Lake Lodge - Public Water Supply #14986 (GPS: N56.50239 - W105.25637)	29-May-2006 Athabasca/Keewatin/Mamawetan		1		Issued due to the presence of E.coli.
Manewan Enterprises Ltd. - Marchel Lake	25-Jun-07 Athabasca/Keewatin/Mamawetan	1			PDWA issued due to poor bacteriological results.
Manewan Enterprises Ltd. - Nemei Lake	17-June-2011 Mamawetan Churchill River HR	1			PDWA issued <b>June 24, 2011</b> .
Meadow's Edge Bed and Breakfast Well, RM of Preeceville #334 - Facility #21301, NE 11-35-6 W2M	30-Jul-2009 Sunrise HR	1			PDWA issued due to the presence of bacteria.
Milton Lake Lodge - Public Water Supply 15324-GPS: latitude/longitude: 59.5/103.867	26-June-06 Athabasca/Keewatin/Mamawetan		1		EBWO issued on <b>June 27, 2006</b> due to the presence of E.Coli.
Minor Bay Lodge & Outposts Ltd. - Premise #15012	22-June-10 Mamawetan Churchill River HR	1			PDWA issued <b>June 24, 2010</b> .
Missy's Restaurant - Margo SK SW15-33-10W2	2011-08-11 Saskatoon Health Region	1			PDWA issued <b>August 11, 2011</b> : coliform bacteria present in recent water samples.
Morning Lake Outfitters - Public Water Supply #16118	14-June-07 Athabasca/Keewatin/Mamawetan		1		EBWO issued <b>June 13, 2007</b> due to the presence of total coliform and E.Coli.
Navau Trailer Park, Weyburn	23-June-11 Sun Country HR		1		EBWO issued on <b>June 23, 2011</b> due to flooding.
Northern Echo Lodge - Public Water Supply 13963	26-June-06+B108 Athabasca/Keewatin/Mamawetan		1		EBWO issued on <b>June 27, 2006</b> due to the presence of E.Coli.
North Prairie RM Well (located at NE 8-36-6 W2nd within the RM of Preeceville # 334)	30-Oct-2009	1			PDWA issued on <b>October 30, 2009</b> due to the presence of coliform bacteria.
Northern Reflection Lodge - Premise #15265	22-June-2010 Mamawetan Churchill River HR	1			PDWA issued <b>June 24, 2010</b> .
O'Brien's Fly-in Careen Lake Lodge - Kitchen Tap; Premise 16081; Lat/Long: 56.9783/108273	13-June-2008 Athabasca/Keewatin/Mamawetan	1			PDWA issued due to the presence of coliform bacteria.
Oliver Lake Lodge - Premise #14071 - Log/Lat: 56.8648 / 103.398	15-July-2008 Athabasca/Keewatin/Mamawetan		1		EBWO issued due to the presence of E.Coli.
Osin Community Well	14-Sep-07 Sunrise HR	1			PDWA issued due to the presence of coliform.
Oyama Regional Park - Well	16-July-09 Regina Qu'Appelle HR		1		EBWO issued <b>July 16, 2009</b> due to the presence of contaminants, namely, E coli bacteria in the public water supply.
Paull River Wilderness Camps (Premise # 12523)	17-June-2009 Athabasca/Keewatin/Mamawetan		1		EBWO issued due to the presence of coliform bacteria and ecoli.
Pawistik Lodge - Hanson Lake Road - KM 271	4-June-2002 Mamawetan Churchill River HR		1		EBWO issued <b>June 4, 2002</b> lacks minimum treatment.

Phantom Lake Golf Club Inc.	1-Aug-2010 Mamawetan Churchill River HR	1			PDWA issued on <b>August 1, 2010</b> due to total coliforms.
Phil Foster Wilderness Fishing	25-June-07 Athabasca/Keewatin/Mamawetan	1			PDWA issued due to poor bacteriological results.
Pickeral Bay Cabins Premise #15268	11-June-2010 Mamawetan Churchill River HR		1		EBWO issued <b>June 11, 2010</b> .
Pilot Butte Recreation Centre	3-Oct-2011	1			PDWA issued <b>October 3, 2011</b> due to the presence of coliforms.
Pilot Butte Tempo	21-Aug-2009 Regina Qu'Appelle HR	1			PDWA issued on <b>August 21, 2009</b> due to the presence of coliform bacteria in the public water supply.
Pilot's Lodge - Public Water Supply #17110	1-July-07 Athabasca/Keewatin/Mamawetan		1		EBWO issued due to the presence of total coliform and E.Coli.
Pine Point Lodge & Outpost - Public Water Supply 14162	8-June-2007 Athabasca/Keewatin/Mamawetan	1			PDWA issued due to poor bacteriological results.
Pipestone Lake Fishing Lodge Inc.	25-Jun-07 Athabasca/Keewatin/Mamawetan	1			PDWA issued due to poor bacteriological results.
Pointer Lake Lodge	4-June-2010 Mamawetan/Churchill River RHA	1			PDWA issued on <b>June 4, 2010</b> due to the presence of contaminants in a water sample, namely coliforms.
Prairie Lake Regional Park (RM of Victory #226) NW 16-20-10 W3rd	21-May-2010 Heartland HR	1			PDWA issued effective <b>May 21, 2010</b> due to the distribution of untreated surface water drawn from Diefenbaker Lake.
Preeceville, RM of (Lady Lake Well, Facility 13803 NW 23-35-5-W2nd	28-June-07 Sunrise HR		1		EBWO issued due to presence of total coliform and E.Coli.
Prill Lake Lodge - Premise 15899; Long/Lat: 58.0076/108.685	13-June-2008 Athabasca/Keewatin/Mamawetan	1			PDWA issued due to the presence of total coliform.
R & R Wilderness Lodge (Premise #14036 Latitude/Longitude 56.2667/106.817)	5-June-2009 Athabasca/Keewatin/Mamawetan	1			PDWA issued due to the presence of total coliform.
Readlyn	30-Jul-2009 Five Hills HR	1			PDWA issued due to inability to meet minimum chlorine residuals, lack of automatic disinfection equipment, and potential for contamination of source water due to deteriorated well house
Reciprocity, RM of #32 Well #3	6-July-11 Sun Country HR		1		EBWO issued <b>July 6, 2011</b> due to the presence of E coli.
Riverside Hotel in Gainsborough	21-Dec-09 Sun Country HR	1			PDWA issued on <b>December 21, 2009</b> due to lack of minimum treatment.
Russell Hansons Mounted Police Museum-Water Supply Facility #: 24917	21-July-11 Saskatoon HR	1			PDWA issued <b>July 21, 2011</b> due to lack of minimum treatment.
Russell's Churchill River Camps - Public Water Supply #13982	9-June-2007 Athabasca/Keewatin/Mamawetan	1			PDWA issued due to poor bacteriological results.
Russell's Churchill River Camp Ltd. - Scotties Beach - Public Water Supply 13972	25-Jun-07 Athabasca/Keewatin/Mamawetan		1		EBWO issued <b>June 25, 2007</b> due to the presence of E.Coli.
Russell's Churchill River Camp Ltd. - Kamuchawie Lake - Public Water Supply 13978	5-July-07 Athabasca/Keewatin/Mamawetan		1		EBWO issued due to the presence of total coliform and E.Coli.
Saltcoats RM of #213 Well #1, NW 13-24-3-W2nd	10-Oct-07 Sunrise HR		1		EBWO issued due to the presence of coliform bacteria.
Scott Lake Lodge Ltd. - Public Water Supply #15144	13-July-2010 Athabasca/Keewatin/Mamawetan		1		EBWO issued on <b>July 13, 2010</b> due to the presence of contaminants, namely coliforms and E. coli.
Shannon Lake Campground - Cistern RM of Three Lakes #400 SE 30-42-24 W2nd	16-April-2010 Saskatoon HR	1			PDWA issued effective <b>April 16, 2010</b> due to a lack of compliance in regards to water sampling.
Silence of the North Hunting & Fishing Inc. PW#12159	27-July-2011 Mamawetan Churchill River HR	1			PDWA issued on <b>July 27, 2011</b> : total coliforms present.
Sliding Hills, RM of - #273 Petriw Well	13-July-07 Sunrise HR	1			PDWA issued due to high nitrate levels.
Sliding Hills, RM of #273, Sliding Hills Community Well #1 (Donwell) - Premise # 13625 SE 9-30-3 W2nd	10-July-09 Sunrise HR		1		PDWA issued <b>July 10, 2009</b> due to the presence of bacteria and replaced on <b>October 7, 2010</b> with an EBWO due to the presence of both total coliform and E.coli bacteria in the water supply.
Slim's Cabins - Golden Lake PW#23568	20-June-2011 Mamawetan Churchill River HR	1			PDWA issued effective <b>June 20, 2011</b> .
Slim's Cabins - Kamuchawie Lake	20-June-11 Mamawetan Churchill River HR	1			EBWO issued <b>July 4, 2007</b> due to E. coli detected in drinking water system.

Slim's Cabins - Kipahigan Lake PW#13956	10-June-11 Mamawetan Churchill River HR		1		PDWA issued <b>June 20, 2011</b> .
Slim's Cabins - Tomahawk Lake Outpost PW#12418	20-June-11 Mamawetan		1		EBWO issued <b>June 20, 2011</b> .
South Bay Outfitters Ltd. (GPS: N54.3426 W105.8750)	9-Aug-2010 Mamawetan HR		1		EBWO issued due to the presence of E.coli.
Spring Bay Lodge PW #15127	13-July-2010 Mamawetan Churchill River HR				PDWA issued on <b>July 13, 2010</b> due to the presence of contaminants, namely, total coliforms.
Suffern Lake Regional Park Well #2 (S 1/2, 25-42-28 W2nd)	24-Jun-2009	1			PDWA issued due to the presence of coliform bacteria.
Sunshine Fairways SE1/4 33-52-7 W3rd RM of Canwood #494	12-Aug-09 PA Parkland HR	1			PDWA issued due to failure to submit water results.
Swede's Bed'N Breakfast Foam Lake	20-June-08 Sunrise HR	1			PDWA issued due to the presence of total coliform bacteria and lack of water sampling.
T & D Amisk Cabins Ltd	1-Aug-10 Mamawetan Churchill River HR	1			PDWA issued on <b>August 1, 2010</b> due to total coliforms.
Tank's Country Meats - Well SE 18-22-6 W2nd	14-Dec-07 Sunrise HR	1			PDWA issued due to the presence of coliform bacteria.
The New Canoe Lake West Resort 1987	11-Sept-2010 Athabasca/Keewatin/Mamawetan	1			PDWA issued on <b>September 11, 2010</b> due to total coliforms.
Tate Island Lodge PW #14080	19-July-2008 Mamawetan Churchill River HR		1		PDWA issued effective <b>July 19, 2008</b> .
Theodore Motel Hotel in Theodore	7-March-08 Sunrise HR	1			PDWA issued <b>March 7, 2008</b> . Records indicate the required number of water samples are not being submitted for bacteriological analysis.
Three Flags Motorsport Premises Number PW#21936	25-Aug-2010 Regina Qu'Appelle HR	1			PDWA issued <b>August 25, 2010</b> due to the presence of E. coli bacteria in the public water supply.
Thompson's Camps - Daly Lake Outpost - Premise #15576	23-June-2009 Athabasca/Keewatin/Mamawetan	1			PDWA issued on <b>June 23, 2009</b> due to the presence of coliforms.
Thompson's Camps - Upper Foster Lake Outpost - Premise #16540	20-June-2009 Athabasca/Keewatin/Mamawetan	1			PDWA issued on <b>June 23, 2009</b> due to the presence of coliforms.
Thompson's Camps - Daly Lake Outpost Premise #15576	16-June-2010 Mamawetan Churchill River HR		1		EBWO issued <b>June 24, 2010</b> .
Thunder Mountain Outfitting - Premise #21930	6-Jun-09 Athabasca/Keewatin/Mamawetan		1		EBWO issued due to presence of E.Coli and Total Coliform.
Top of the Rock Adventures PW #23552	17-June-2010 Mamawetan Churchill River HR				PDWA issued due to the presence of contaminants in a water sample, namely total coliform.
Touchwood, RM of #248 Well located on NW 18-25-17 W2nd	19-July-11 Regina Qu'Appelle HR		1		EBWO issued <b>July 19, 2011</b> due to contamination by coliform bacteria and E. coli compromising the safety of the well.
Tourist Camp & Campground located on the NW corner Canoe Lake, off Hwy. 903, approx. 20 km from Cole Bay	3-Jul-2002		1		EBWO issued when a repeat sample submitted to the Provincial Laboratory on <b>July 3, 2002</b> was found to contain E.Coli. Bacteria.
Tower Lodge Outfitters - Public Water Supply #16108	14-July-09 Athabasca/Keewatin/Mamawetan		1		PDWA issued due to the presence of total coliform. PDWA lifted on <b>July 16, 2009</b> and upgrade to EBWO due to the presence of ecoli.
Triveet Lake Lodge; Premise #14975; Lat/Long: 54.41776/103.13331	21-June-08 Athabasca/Keewatin/Mamawetan	1			PDWA issued due to the presence of total coliform.
Trout Lake Lodge - Public Water Supply #15276	01-June-06 Athabasca/Keewatin/Mamawetan	1			PDWA issued due to poor bacteriological results.
True North Lodge - Premise 17361, Keller Lake	20-June-08 Athabasca/Keewatin/Mamawetan		1		EBWO issued on <b>June 20, 2008</b> due to the present of total coliform and E.Coli.
Tuffnell Recreation Centre	18-Oct-07 Sunrise HR		1		EBWO issued due to the presence of total coliform and E.Coli.
Tuxford Rural Water Supply	6-July-09 Five Hills HR	1			PDWA issued <b>July 6, 2009</b> due to failure of pipeline operator to submit the required water samples.
Twin Bay Lodge Ltd. PW #16112	2-Sept-2011 Mamawetan Churchill River		1		EBWO issued <b>September 2, 2011</b> due to total coliform and E coli.
Ubiquity Lake Outfitters	25-June-2007 Mamawetan Churchill River HR		1		On <b>April 10, 2008</b> , Mamawetan Churchill River HR advised that the EBWO was issued on June 25, <b>2007</b> due to the presence of E. Coli.
V.J. Fishing Camp - Public Water Supply 12608	8-June-2007 Athabasca/Keewatin/Mamawetan	1			PDWA issued due to poor bacteriological results.
Verwood Water Inc. Premise (ID 16364 - Hamlet of Verwood)	5-Aug-08 Five Hills Health Region	1			PDWA issued due to the inability to meet minimum chlorine residuals, potential for contamination of source water due to deteriorated well house, intermittent unsatisfactory sample results.
Wolverine, RM of #340 - Community Well #1 SE 1-35-24 W2nd	28-Aug-2009 Saskatoon HR	1			PDWA issued on <b>August 28, 2009</b> , water supply has been found to be contaminated with coliform bacterial.

Wood Mountain Regional Park Pool Well Premise Id 11262	18-June-2010 Five Hills HR	1			PDWA issued on <b>June 18, 2010</b> due to persistent total coliforms in submitted water samples.
Wood Mountain Regional Park Shower Well Premise #11263	10-June-11 Five Hills HR	1			PDWA issued <b>June 10, 2011</b> due to a lack of disinfection residual and elevated turbidity levels.
York Lake Golf & Country Club	17-May-2011 Sunrise HR		1		EBWO issued <b>June 30, 2011</b> : E. coli bacteria present in public water supply.
<b>Advisories/Orders Currently in Effect:</b>		<b>108</b>	<b>65</b>	<b>0</b>	